

FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E




FIG. 4

表記 外觀状態	F	E	D	C	B	A
ボイド割合	80%以上	60%程度	40%程度	20%程度	10%程度	5%以下
	